



Example Report



			MEDICAL VACUUM	OXYGEN	NITROUS OXIDE	CARBON DIOXIDE	MEDICAL AIR	Remarks
Theater								
	Theater 1	1	✓	Leak	✓	✓	✓	O-Ring on Wall Supply
	Theater 2	1	✓	✓	✓	✓	✓	Clear
	Theater 3	1	✓	✓	✓	✓	✓	Clear
	Theater 4	1	✓	✓	✓	✓	✓	Clear
	Theater 5	1	Leak	✓	✓	✓	✓	O-Ring on Overhead Supply
	Theater 6	1	✓	✓	✓	✓	✓	Clear
	Theater 7	1	✓	✓	✓	✓	✓	Clear
Plant Room								
	Plant	N/A	✓	✓	✓	N/A	Leak	Receiver Pressure release Valve
	Plant	N/A	✓	✓	✓	N/A	Leak	Domnick Hunter Filter No 1
	Plant	N/A	✓	✓	✓	N/A	Leak	Domnick Hunter Filter No 3

			MEDICAL VACUUM	OXYGEN	Remarks
Pediatric Ward					
	Ward A	3	Leak	✓	Bed 2 Vacuum Valve Open
	Ward B	5	✓	✓	Clear
	Ward C	5	✓	✓	Clear
	Ward D	2	✓	✓	Clear
	Treatment Room	1	✓	✓	Clear
Medical Ward					
	Ward A	3	✓	✓	Clear
	Ward B	3	✓	Leak	Bed 1 Leak at receptical O-Ring
	Ward C	1	✓	Leak	Bed 1 Leak at receptical O-Ring
	Ward D	1	✓	✓	Clear
	Ward E	3	✓	✓	Clear
	Ward F	2	✓	✓	Clear
	Ward G	2	✓	✓	Clear
	Ward H	5	✓	✓	Clear
	Ward I	5	✓	Leak	Bed 5 Valve Glass Craked
	Ward J	5	✓	✓	Clear
	Ward K	5	✓	✓	Clear
	Sluice	N/A	✓	N/A	Clear
Surgical Ward 2					
	Ward A	5	✓	✓	Clear
	Ward B	5	✓	✓	Clear
	Ward C	5	✓	✓	Clear
	Ward D	2	✓	✓	Clear
	Ward E	2	✓	✓	Clear
	Ward F	2	✓	✓	Clear
	Ward G	2	✓	✓	Clear
	Ward H	2	✓	Leak	Bed 1 Leak at receptical O-Ring
	Ward I	2	✓	Leak	Bed 2 Valve Faulty
	Ward J	2	✓	✓	Clear
	Ward K	5	✓	✓	Clear
	Ward L	5	Leak	✓	Bed 3 Valve Faulty
Cath Lab					
	Waiting Area	1	✓	✓	Clear
	Cath Unit	1	Leak	✓	Valve Left Open
Surgical Ward 1					
	Ward A	5	Leak	✓	Bed 1 Valve left Open
	Ward A	5	Leak	✓	Bed 3 Valve Left Open
	Ward B	5	✓	Leak	Bed 2 Faulty O-Ring



	Ward C	5	√	√	Clear
Surgical Ward 3	Room	No of Beds			Remarks
	Ward A	4	√	√	Clear
	Ward B	2	√	√	Clear
	Ward C	1	√	√	Clear
	Ward D	5	Leak	√	Bed 4 Valve Left Open
	Day Ward	6	√	√	Clear

			MEDICAL VACUUM	OXYGEN	MEDICAL AIR	
Adult ICU	Room	No of Beds				Remarks
	Ward 2 - 10	8	√	√	√	Clear
	Ward 13 - 23	11	√	Leak	√	Bed 15 Leak at O-Ring
	Ward 4 - 9	6	√	√	√	Bed 7 Leak at O-Ring
	Ward 4-9		Leak	√	√	Bed 9 Vacuum Valve Left Open
	Isolation 1	1	Leak	√	√	Valve Left Open
	Isolation 11	1	Leak	√	√	Valve Left Open
	Isolation 12	1	√	Leak	√	Receptical O-Ring Faulty
	Isolation 16	1	Leak	√	√	Valve Left Open
	Isolation 17	1	√	√	√	Clear
	Sluice	N/A	√	N/A	N/A	Clear
Maternity Ward	Room	No of Beds				Remarks
	Ward A	1	Leak	√	N/A	Valve Left Open
	Ward B	1	√	√	N/A	Clear
	Ward C	1	√	√	N/A	Clear
	Ward D	3	Leak	√	N/A	Bed 1 Valve left Open
	Delivery Room 1	1	√	√	√	Clear
	Delivery Room 2	1	√	√	√	Clear
	Delivery Room 3	1	√	√	√	Clear
Neonatal ICU	Room	No of Beds				Remarks
	Nursery	5	Leak	√	√	Bed 1 Valve left Open
	Ward	6	Leak	√	√	Bed 6 Valve Left Open
	Isolation	2	Leak	√	√	Bed 1 Valve left Open
High Care Unit	Room	No of Beds				Remarks
	Ward I	2	√	√	√	Clear
	Ward J	2	√	√	√	Clear
	Ward K	5	√	√	√	Clear
Casualty Department	Room	No of Beds				Remarks
	GI Unit	1	√	√	√	Clear
	Minor Theater	1	√	Leak	√	Valve Glass Leaking
	Waiting Area	3	√	√	√	Clear
Trauma Unit	Room	No of Beds				Remarks
	Bay 1	1	√	√	√	Clear
	Bay 2	1	√	√	√	Clear
	Bay 3	1	√	√	√	Clear